

Make coating defect marking easy and accurate

Using your Coating Defect Labels

1. Inspect your coating.
2. Use the measurement and size gauge to determine the severity of the defect for repainting.
3. Mark any relevant notes and information to the rework team on the label.
4. Put the date on the label.
5. Indicate with an arrow where the defect is.
6. Mark the label location on your report.
7. When the rework team arrives, they can easily remove the label without leaving any residue and will cause no extra work.



Call Blast-One today to order your Coating Defect Labels