



How do I test for dust embedment contamination on my blasted surface?

The Test Procedure



1. Apply an 8" (200mm) piece of tape to a representative test site. Starting at one end of the tape, maintaining a firm pressure and at a constant speed, move the thumb along the tape 3 times in each direction (each stroke should take 5-6 seconds).



2. Remove the tape from the test surface, place on display board and adhere tape to board.

3. Assess the quantity of dust on the tape by visually comparing an area of the tape with equivalent sized areas of the pictorial reference guide. Record the rating (0-5) that closely corresponds to the reference.

Call Blast-One today for more information on dust contamination testing