

Is your Air clean?

Recommended check intervals


Test for air cleanliness:

- before commencement of blasting
- about every 4 hours of continual blasting.

The Blotter Paper Method to check air cleanliness.....

7 Simple Steps:

1. Ensure appropriate safety precautions are in place – safety goggles etc.
2. Set up the blast equipment and start-up the compressor.
3. Secure the test paper apparatus.
4. When the compressor is warmed up, start the blast equipment running with NO abrasive in the airstream.
5. Position the nozzle so it is firing at the centre and within 600mm of the test sheet.
6. Continue the test for 2 minutes.
7. Shut off the air supply and quickly check the test paper for any visual sign, feel or smell of oil, moisture or other contaminants.



DISCLAIMER: The above information and procedure does not nor shall not be taken as representing not intending to be an approved nor a complying nor a standard method nor procedure for testing compressed air quality. It is the responsibility of the reader and/or users of this information to separately determine and verify the correct method and procedure for testing compressed air quality as directed or required or indicated by any work specification or order or other standards. Blast-One™ expressly disclaims any liability for the use or misuse of the above information and procedure.