



BLASTECH

MASTERFIELD
INDUSTRIAL EQUIPMENT

Differential Pressure

A COMMON CAUSE OF DIFFERENTIAL PRESSURE IS BECAUSE THE POT IS CHOKED



- **Use a correctly sized and constructed air dryer to rid yourself of moisture problems** – the largest contractors swear they would never go to a job site with out one. No matter where they are in the country.
- **Do a pressure loss audit all the way from your compressor to your nozzle.** Find out where the pressure is being lost and fix it.
- **Follow a strict maintenance schedule.** Ensure that all your valves, pop up seals and gaskets are sealing properly.
- **Check the ball valve on your blast pot every day** – is it choked - even a little? You could learn something is wrong.

Ph 1800 882 229

Email sales.au@blast-one.com

Web www.blast-one.com.au