

# How can I increase my productivity and efficiency?

## 16 ways to improve your blast cleaning system

*Are you maximising your profits?*

CHECK

- |  |  |
|--|--|
| <input type="checkbox"/> 1. Install a MicroValve                             | <input type="checkbox"/> 9. Screw in a lightweight, long life blast nozzle   |
| <input type="checkbox"/> 2. Take off your old moisture trap                  | <input type="checkbox"/> 10. Dead Man controls – does yours act fast enough? |
| <input type="checkbox"/> 3. Use a bull hose to supply air to your pot        | <input type="checkbox"/> 11. Let's look at your blast pot                    |
| <input type="checkbox"/> 4. Check your nozzle pressure regularly             | <input type="checkbox"/> 12. Keep your cool with a helmet air cooler         |
| <input type="checkbox"/> 5. Blast with a low dust abrasive: Blast-One Garnet | <input type="checkbox"/> 13. Wind up your pressure                           |
| <input type="checkbox"/> 6. Use a lightweight, comfortable helmet            | <input type="checkbox"/> 14. Monitor and purify your breathing air           |
| <input type="checkbox"/> 7. Make sure your compressor is big enough          | <input type="checkbox"/> 15. Use a communication system                      |
| <input type="checkbox"/> 8. Fit a large bore flexible whip hose              | <input type="checkbox"/> 16. Recycle your abrasive                           |

---

**Call Blast-One today to order your FREE '16 Ways' booklet**