

Get the most out of your “BlastJet Daily Component & Work Area Checklist”

Be a step ahead. Complete your BlastJet Checklist every day!

FRONT PAGE


STEP 1
Fill out relevant details

STEP 2
Check Blast Components

STEP 3
Check Operator Safety Components

STEP 4
List all items that need replacing
Check items against your Catalogue and note Part Number.
Call or email Blastmaster for immediate despatch.

Use this diagram for locations



BACK PAGE

STEP 1
Fill in Job, Company Details, etc

STEP 2
Hazard Number

STEP 3
Describe Hazard (eg. hose across ground)


STEP 4
Identify Category from the chart

STEP 5
Identify likelihood and seriousness of the consequences to identify the Risk Rating from the RR Chart

STEP 6
Indicate the safety precautions that must be put in place. Finally, record this data for compliance matters in your project file.

STEP 7
Reassess Rating with Safety Precautions in place. All hazards must be reduced to low risk rating.

Class of Risk



Call Blast-One today for all your blast jetting needs