


17 ways to blast tank floors faster

- 1** Always blast from the middle and work your way out.
- 2** Keep the spent abrasive dispersing as you go.
- 3** Blast columns as you get to them.
- 4** Clean up abrasive from the outer edge.
- 5** Complete final touch up of edge.
- 6** Thoroughly vacuum the tank to avoid contamination.



Call Blast-One today for more information on efficient blasting techniques